

Call AL-KO on 1800 035 603 or speak with your AL-KO representative or view the entire product range at www.alko.com.au



JET SERIES WATER PUMP PRODUCT ANNOUNCEMENT

ALKO International would like to make you aware of a product support issue on the JET SERIES Waterpumps .

Problem – A small number of JET601 and JET802 have been received with slightly loose ‘head bolts’.

Solution – **TIGHTEN 4 HEAD BOLTS IF ANY LEAK OCCURS.**

Switch pump off, remove inlet pipe or hose. On the front of the Jet Pump, a black polypropylene head is held onto the body by four (4) allen head bolts.

Tighten each allen head bolt with a standard, correct size allen key until tight.

DO NOT OVER TIGHTEN WITH MECHANICAL OR AIR PRESSURE MECHANISM.

Once tight, replace inlet pipe or hose and resume use.

All screw on connections should have a liberal amount of Teflon tape applied to ensure proper and secure fitment.

This problem is restricted to a batch of Jet Pumps that have been received by AL-KO, and the above recommendation will NOT void any warranty.

AL-KO will also provide replacement head seal FOC if required.

If you have any further queries, please contact your local AL-KO office on **1800 035 603** or email info@alko.com.au

**ALKO WOULD ALSO LIKE TO THANK OUR
CUSTOMERS FOR THEIR SUPPORT**